

DR Power Equipment Recalls Leaf Blowers and Leaf Vacuums Due to Laceration Hazard



Recalled DR Power Equipment walk-behind leaf blower













Name of Product:

Walk-Behind Leaf Blowers and Vacuums, and Tow-Behind Leaf Vacuums

Hazard:

Pieces from the recalled leaf blowers and vacuums can come loose inside the unit and be ejected, posing a laceration hazard to users and bystanders.

Remedy:

Repair

Recall Date:

May 02, 2024

Units:

About 57,200 (In addition, about 956 were sold in Canada)

Consumer

Contact

DR Power LLP toll-free at 877-221-4038 from 8:30 a.m. to 5 p.m. ET Monday through Friday, email at recall@drpower.com, or online at https://drpower.com/recalls or https://www.drpower.com/ and click on "Product Recalls" at the bottom of the page for more information.

Recall Details

In Conjunction With:



Description:

This recall involves DR Power Equipment walk-behind leaf blowers and vacuums, and towbehind leaf vacuums with the following model numbers:

Unit Type		Model Numbers	
Walk-	LB16020DEN	LB16020DMNR	
Behind Leaf	LB16020DENR	LB18020DEN	
Blower	LB16020DMN	LB18020DENR	
Walk-	WL33006DMN	WL35008DENSD	
Behind	WL33006DMNR	WL35008DMN	
Leaf	WL35008DEN	WL35008DMNR	
Vacuum	WL35008DENR	WL35008DMNSD	
Tow-	LL31027DMN	LL33032DEN	LL33032DENR
Behind	LL33032DFNSD	LL33032DMN	LL35045DFN

LL33032DMN

LL33032DENSD

LL35045DEN

11.0°4 T	DK Fowel Equipment Recans Lear Blowers and Lear Vacuums Due to Laceration Hazard 1 CFSC.gov			
Unit Type		Model Numbers		
LL3	LL35045DMN	LL35045DMNR	LL37045DEN	
	LL37045DMN	LL37045DMNR	LL37045DMNSD	
	LL37060DEN	LL37060DENR		
	LL21009DMN	LL21009DMNR	LL21009DMNSD	
	LL23009DEN	LL23009DENR	LL23009DENSD	
Tow-	LL23009DMN	LL23009DMNR	LL23009DMNT	
Behind	LL25013DEN	LL25013DENR	LL25013DENSD	
LL2	LL25013DMN	LL25013DMNR	LL25013DMNSD	
	LL27016DEN	LL27016DENR	LL27016DENSD	
	LL27016DMN	LL27016DMNR	LL27016DMNSD	
Additional	LLVX13EDTDV3BF1	LLVX13EDTDVBBF1	LLVX13ENTDV3BF3	
LL2 Models	LLVX13ENTDVBBF3	LLVX13MDTDV3BF0	LLVX13MDTDV3BF1	
*Note:	LLVX13MDTDVBBF1	LLVX13MNTDV3BF3	LLVX13MNTDVBBF3	
These	LLVX16E	LLVX16EDTDV3BF1	LLVX16EDTDVBBF1	
model	LLVX16ENTDV2BF3	LLVX16ENTDV3BF3	LLVX16ENTDVBBF3	
numbers	LLVX16MDTDV2BF1	LLVX16MDTDV3BF1	LLVX16MDTDVBBF1	
may or may not	LLVX16MNTDV2BF3	LLVX16MNTDV3BF3	LLVX16MNTDVBBF3	
have	LLVX9AMDTDVBBF3	LLVX9AMNTDVBBF3	LLVX9GMNTDVBBF3	

Unit Type		Model Numbers	
spaces as	LLVXX9EDTDV3BF1	LLVXX9EDTDVBBF1	LLVXX9ENTDV3BF3
printed on the	LLVXX9ENTDVBBF3	LLVXX9MDTDV3BF1	LLVXX9MDTDVBBF1
data tags.	LLVXX9MNTDV3BF3	LLVXX9MNTDVBBF3	LLVXX9MNTDVBTF3

DR is printed on the motor housing. The model number on the walk-behind leaf blower is located on the top at the back of the blower housing. The model number on the walk-behind leaf vacuum is located on the front right side of the unit behind the wheel. The model number on the tow-behind leaf vacuum is on the impeller housing beside the engine.

Remedy:

Consumers should immediately stop using the recalled leaf blowers and vacuums, and contact DR Power for a free dealer-installed repair.

Incidents/Injuries:

The firm has received 22 reports of loose pieces being ejected from the units. No injuries have been reported.

Sold At:

Independent power equipment stores nationwide and online at drpower.com from September 2014 through January 2024 for between \$1,300 and \$4,000.

Manufacturer(s):

Generac Power Systems Inc., of Waukesha, Wisconsin

Distributor(s):

DR Power Equipment, of South Burlington, Vermont

Manufactured In:

United States

Recall number:

24-222

Fast Track

Recall

Note: Individual Commissioners may have statements related to this topic. Please visit www.cpsc.gov/commissioners to search for statements related to this or other topics.

Recall Complaint

If you are experiencing issues with a recall remedy or believe a company is being non-responsive to your remedy request, please use this form and explain the situation to CPSC.