

 An official website of the United States government [Here's how you know](#) ▾



DR Power Equipment Reannounces and Expands Recall of Leaf Vacuums Due to Laceration Hazard; New Remedy Available



Recalled DR Power Equipment walk-behind leaf vacuum



Name of Product:

Walk-Behind Leaf Vacuums and Tow-Behind Leaf Vacuums

Hazard:

Pieces from the recalled leaf vacuums can come loose inside the unit, or debris can pierce the chute, resulting in material ejecting and posing a laceration hazard to users and bystanders.

Remedy:

Repair

Recall Date:

January 08, 2026

Units:

About 60,250 (In addition, about 1,023 were sold in Canada) DR Power Equipment previously recalled 57,200 leaf blowers and vacuums in [May 2024](#). New models of leaf vacuums have been added to this recall.

Consumer Contact

DR Power LLP toll-free at [877-221-4038](tel:877-221-4038) from 8:30 a.m. to 5 p.m. ET Monday through Friday, email at recall@drpower.com, or online at <https://www.drpower.com/LLV-FreeRepairKit> or <https://www.drpower.com/> and click on “Product Recalls” at the bottom of the page for more information.

Recall Details

In Conjunction With:



Description:

This recall involves DR Power Equipment walk-behind leaf vacuums and tow-behind leaf vacuums with the following model numbers:

Unit Type	Model Numbers
Walk	
Behind	
Leaf	
Vacuum	
	WL33006DMN WL35008DENSD
	WL33006DMNR WL35008DMN
	WL35008DEN WL35008DMNR
	WL35008DENR WL35008DMNSD
	WL33106DMN WL35108DEN
	WL33106DMNR WL35108DENR
	WL35108DENSD

Tow
Behind
LL3

LL31027DMN	LL33032DEN	LL33032DENR
LL33032DENSD	LL33032DMN	LL35045DEN
LL35045DMN	LL35045DMNR	LL37045DEN
LL37045DMN	LL37045DMNR	LL37045DMNSD
LL37060DEN	LL37060DENR	LL37145DEN
LL31127DMN	LL33132DMN	LL37160DEN
LL31127DMNR	LL33132DMNR	
LL33132DEN	LL35145DEN	
LL33132DENSD	LL35145DMN	

Tow**Behind****LL2**

LL21009DMN	LL21009DMNR	LL21009DMNSD
LL23009DEN	LL23009DENR	LL23009DENSD
LL23009DMN	LL23009DMNR	LL23009DMNT
LL25013DEN	LL25013DENR	LL25013DENSD
LL25013DMN	LL25013DMNR	LL25013DMNSD
LL27016DEN	LL27016DENR	LL27016DENSD
LL27016DMN	LL27016DMNR	LL27016DMNSD

Additional LL2 Models

*Note: These model numbers may or may not have spaces as printed on the data tags.

LLVX13EDTDV3BF1	LLVX13EDTDVBBF1	LLVX13ENTDV3BF3
-----------------	-----------------	-----------------

LLVX13ENTDVBBF3	LLVX13MDTDV3BF0	LLVX13MDTDV3BF1
LLVX13MDTDVBBF1	LLVX13MNTDV3BF3	LLVX13MNTDVBBF3
LLVX16E	LLVX16EDTDV3BF1	LLVX16EDTDVBBF1
LLVX16ENTDV2BF3	LLVX16ENTDV3BF3	LLVX16ENTDVBBF3
LLVX16MDTDV2BF1	LLVX16MDTDV3BF1	LLVX16MDTDVBBF1
LLVX16MNTDV2BF3	LLVX16MNTDV3BF3	LLVX16MNTDVBBF3
LLVX9AMTDVBBF3	LLVX9AMNTDVBBF3	LLVX9GMNTDVBBF3
LLVXX9EDTDV3BF1	LLVXX9EDTDVBBF1	LLVXX9ENTDV3BF3
LLVXX9ENTDVBBF3	LLVXX9MDTDV3BF1	LLVXX9MDTDVBBF1
LLVXX9MNTDV3BF3	LLVXX9MNTDVBBF3	LLVXX9MNTDVBTF3

“DR” is printed on the motor housing. The model number on the walk-behind leaf vacuum is located on the front right side of the unit behind the wheel. The model number on the tow-behind leaf vacuum is on the impeller housing beside the engine.

Remedy:

Consumers should immediately stop using the recalled leaf vacuums and contact DR Power for a free repair kit that includes a metal outer shield to be bolted onto the existing chute of the recalled leaf vacuums and installation instructions. Consumers can contact DR Power for information and assistance on making the repair. Consumers who responded to the original recall should nevertheless contact DR Power for the new remedy.

Incidents/Injuries:

The firm has received 46 reports of loose pieces being ejected from the units. No injuries have been reported.

Sold At:

Independent power equipment stores nationwide and online at drpower.com from September 2014 through June 2025 for between \$1,300 and \$4,000.

Manufacturer(s):

Generac Power Systems Inc., of Waukesha, Wisconsin

Distributor(s):

DR Power Equipment, of South Burlington, Vermont

Manufactured In:

United States

Recall number:

26-166

Fast Track

Recall