

 An official website of the United States government [Here's how you know](#) ▼



Happy 250th Anniversary, America!



United States
CONSUMER PRODUCT SAFETY COMMISSION

DR Power Equipment Recalls Pilot and Premier Trimmer Mowers Due to Risk of Serious Injury or Death from Fire and Burn Hazards



Recalled DR Power Pilot Trimmer Mower - model T4X1076DMN

**Name of Product:**

DR Power Equipment Pilot and Premier Trimmer Mowers

Hazard:

Grass and debris can accumulate in the trimmer mowers and ignite, posing a risk of serious injury or death from fire and burn hazards.

Remedy:

Repair

Recall Date:

October 08, 2026

Units:

About 42,860 (In addition, about 340 were sold in Canada)

Consumer Contact

DR Power Equipment toll-free at [800-854-3194](tel:800-854-3194) from 8:30 a.m. to 5 p.m. ET Monday through Friday, email at recall@drpower.com or online at <http://drpower.com/recalls> or www.drpower.com and click “Product Recalls” at the bottom of the page for more information.

[Website](#)[E-mail](#)[Phone](#)

Recall Details

In Conjunction With:



Description:

This recall involves DR Power Equipment Pilot and Premier walk-behind trimmer mowers. The trimmer mowers are orange and black and have the DR Power logo on the top of the motor and on the top of the frame above the cutter head. The trimmer mowers are labeled “Premier” or “Pro” on the side of the frame. The model numbers are printed on a label located on the side of the product’s frame.

Recalled model numbers and product description, which include all serial numbers, are listed below.

Model Number	Product Description	Serial Number Range
T4X1076DMN	DR TRIMMER PILOT 7.6 FPT DR MS	All
T4X1076DMNR	DR TRIMMER PILOT 7.6 FPT DR MS RECON	All
T4X1076DMNSD	DR TRIMMER PILOT 7.6 FPT DR MS SD	All
T4X1176DMN	DR TRIMMER PILOT 7.6 FPT DR MS	All
T4X1176DMN-1	DR TRIMMER PILOT 7.6 FPT DR MS	All
T4X1176DMNR	DR TRIMMER PILOT 7.6 FPT DR MS RECON	All
TR43076DMN	DR TRIMMER PREMIER 7.6 FPT DR MS	All

TR43076DMNR	DR TRIMMER PREMIER 7.6 FPT DR MS RECON	All
-------------	---	-----

Remedy:

Consumers should stop using the recalled trimmer mowers immediately and contact DR Power Equipment for a free repair kit. If consumers have concerns about installing the repair kit, contact DR Power Equipment to schedule a free repair installation from an authorized dealer.

Incidents/Injuries:

The firm has received 19 reports of incidents involving the trimmer mowers catching fire, including two reports of minor injuries such as blisters on hands and feet.

Sold At:

Ace, TSC, Bomgaars, other home improvement, hardware and independent power equipment stores nationwide and online at drpower.com from November 2022 through July 2026 for between \$380 to \$550.

Importer(s):

Generac Power Systems Inc., of Waukesha, Wisconsin

Manufactured In:

United States and Vietnam

Recall number:

27-016

Fast Track

Recall

