

 An official website of the United States government [Here's how you know](#) 



[Happy 250th Anniversary, America!](#)



United States
CONSUMER PRODUCT SAFETY COMMISSION

DR Power Equipment Recalls Lawn Mowers Due to Risk of Serious Injury or Death from Laceration Hazard; Violate Mandatory Standard for Lawn Mowers



Recalled DR Walk-Behind Power Lawn Mower

**Name of Product:**

DR Power PRO MAX30 30" Walk-Behind Power Lawn Mowers

Hazard:

The recalled mowers violate the mandatory safety standard for walk-behind power lawn mowers because the blades can operate without the blade control system engaged or continue to operate even after the release of the control, posing a serious laceration hazard.

Remedy:

Repair

Recall Date:

August 06, 2026

Units:

About 320 (In addition, 9 were sold in Canada)

Consumer Contact

DR Power Equipment toll-free at 877-221-4038 from 8:30 a.m. to 5 p.m. ET Monday through Friday, email at recall@drpower.com, or online at <http://www.drpower.com/recalls> or <https://www.drpower.com/> and click on "Product Recalls" at the bottom of the page for more information.

Website

E-mail

Recall Details

In Conjunction With:



Description:

This recall involves DR Power PRO MAX30 30” Deck Wide Cut Walk-Behind Power Lawn Mowers 10.6 FPT, Models: ES (WM25030DEN), MS (WM25030DMN) and MS Recon (WM25030DMNR). The lawn mowers are orange and black and have the “DR” logo printed on the black clippings bag, front guard, and top of the motor. The brand “PRO MAX30” is labeled on the front handlebars. The model and serial number are printed on the left side of the mower in front of the rear wheel. The following models and serial numbers are subject to the recall:

Product	Model	Serial Numbers
DR Power PRO MAX30 10.6 FPT ES	WM25030DEN	3015894821 through 3017342386
DR Power PRO MAX30 10.6 FPT MS	WM25030DMN	3015662325 through 3017342379
DR Power PRO MAX30 10.6 FPT MS Recon	WM25030DMNR	3015913138 through 3015913138

Remedy:

Consumers should stop using the recalled mowers immediately unless they have already received a free repair kit in the mail from DR Power and it has been installed. If the repair kit has not been

installed, contact DR Power to receive updated repair instructions or schedule a free repair from an authorized dealer. Owners who have not received a repair kit should contact DR Power Equipment to receive a free repair kit or schedule a free repair from an authorized dealer.

Incidents/Injuries:

The manufacturer reported 19 incidents involving the mower blades staying engaged or not stopping after release of the blade control. No injuries have been reported.

Sold At:

Independent power equipment stores nationwide and online at drpower.com from September 2024 through September 2025 for between \$1,600 and \$1,800.

Manufacturer(s):

Generac Power Systems Inc., of Waukesha, Wisconsin

Distributor(s):

DR Power Equipment, of South Burlington, Vermont

Manufactured In:

United States

Recall number:

26-648