



United States
**CONSUMER PRODUCT
SAFETY COMMISSION**

DR Power Equipment Recalls Tow-Behind Field & Brush Mowers Due to Fire and Burn Hazards



Recalled DR Power Tow-Behind Field and Brush Mower

**Name of Product:**

Tow-Behind Field & Brush Mowers

Hazard:

The exhaust pipe can break and cause damage to the unit due to excessive heat, especially in the presence of dry cuttings or spilled fuel, posing fire and burn hazards.

Remedy:

Refund

Recall Date:

November 09, 2023

Units:

About 2,930 (In addition, 102 were sold in Canada)

Consumer

Contact

DR Power Equipment at 800-854-1565 from 8:30 a.m. to 5 p.m. ET Monday through Friday, email at recalls@DRPower.com or online at <http://lvtbrc.com/> or www.drpower.com and click on Product Recalls at the bottom of the page for more information.

Recall Details

In Conjunction With:



Description:

This recall involves DR Power Equipment and Generac brand tow-behind field and brush mowers. The following model and serial numbers, printed on a white label that is on the rear frame of the mower near the right rear tire, are included in this recall.

Name	Model Number	Serial Number Range
DR Power Tow-Behind Field and Brush Mower	TB 25044B EN	All serial numbers beginning with TB2, plus 3002188267 to 30024310751
	TB 25044B ENC	30030052232 to 3004525033
	TB 25044B ENR	3004734233, 3004835965, 3005064288, 3005471720,

3005548665, 3007678624,
3008122643

TBM 20A ED TDVE
OF1

All serial numbers
beginning with TB; in
addition, 300275210

TBM 20A EN TDVE
OD3

All

TBM 20A EN TDVE
OF3

All

TBM20AENTDVEOF3

3002188263 to 3002490281

Generac Tow-
Behind Field
and Brush
Mower

TB 25044GENG

3003540054 to 3004428691

Remedy:

Consumers should immediately stop using the recalled mowers and contact DR Power Equipment for a prorated refund or credit toward a new DR Power product. The prorated refund or credit will be determined based on the age of the unit. DR Power is contacting all known purchasers directly.

Incidents/Injuries:

The firm has received 14 reports of fires causing damage to the mowers.

Sold At:

Authorized DR Power Equipment dealers nationwide and online at drpower.com and Generac.com from November 2015 through April 2021 for between \$3,400 and \$4,000.

Manufacturer(s):

DR Power Equipment, of South Burlington, Vermont, a subsidiary of Generac Power Systems Inc., of Waukesha, Wisconsin (through January 2018) and Generac Power Systems, Inc., of Waukesha, Wisconsin (after January 2018).

Manufactured In:

United States

Recall number:

24-022

Fast Track**Recall**

Note: Individual Commissioners may have statements related to this topic. Please visit www.cpsc.gov/commissioners to search for statements related to this or other topics.

Recall Complaint

If you are experiencing issues with a recall remedy or believe a company is being non-responsive to your remedy request, please use this form and explain the situation to CPSC.